



FIG. 1





















206




**ELECTRON BEAM** 






















FIG. 8




FIG. 9A




FIG. 9B






FIG. 10



## FIG. 11



## FIG. 12

URL http://www.maintain.co.jp/db/input.html	
TROUBLE DB INPUT WINDOW	
	-
OCCURRENCE DATE 2000/3/15 ~ 4040	
TYPE OF APPARATUS ******** ~4010	
SUBJECT OPERATION ERROR (START-UP ERROR) ~ 4030	
SERIAL NUMBER S/N 465NS4580001 ~ 4020	
DEGREE OF URGENCY D ~4050	
SYMPTOM	LED IS KEPT FLICKERING AFTER 企
	POWER-ON 4060
REMEDY	POWER ON AGAIN 요.
	(PRESS RED BUTTON IN ACTIVATION) 4070
PROGRESS	INTERIM HAS BEEN DONE
	<u></u> 4080
SEND (RESET) 4100 4110 4120	
1)20	
LINK TO RESULT LIST DATABASE SOFTWARE LIBRARY OPERATING GUIDE	

FIG. 13




FIG. 14

